## **Detailed Call Report with Service Reports**



Date 09/09/2021 Page 1 of 1

Call	Call	Call															
Number	Status	Type	Call In Date/Time			Α	Arrival Date/Time		Comp Date/Time			Site Number		Site Name			
66729 COMP Serial Number:		CON +					07/09/2021 14:35:00 Product Number: AVS		08/09/2021 10:00:00			SOUT004-0001 Area: SE		South Cambridgeshire District Engineer: 062			
Expe	tact Name: ected Resp blem: <sub>Tryin</sub>			1.5kg	ı <b>r</b> udio is	0 <b>min</b> not going				752470 0.43	Site <sup>-</sup>	Γime:		0.58	Lapse	Time:	4.35
FSR	Num: 1	Starte	ed:	07/09/2	021 14	:35:00	Complete	<b>d:</b> 07/09	9/2021 14	:40:00	Engineer	: 062	Ü	Fault:	AUD	Repair:	21
Solu		Got them temporarily up and running so that they could hold their meeting. Aaron to call me when meeting is finished so that investigations car be completed.															
FSR	Num: 2	Starte	ed:	08/09/2	021 09	:30:00	Complete	<b>d:</b> 08/09	9/2021 10	0:00:00	Engineer	: 062		Fault:	999	Repair:	99
Solu		fered to sup											ter yester	rday's i	ssues.	Logged on	and